

Oil Field Environmental Incident Summary

Incident: 20150809080346 **Date/Time of Notice:** 08/09/2015 08:03
Responsible Party: HRC OPERATING, LLC
Well Operator: HRC OPERATING, LLC
Well Name: BORRUD 156-101-2B-11-3H
Field Name: TYRONE **Well File #:** 29238
Date Incident: 8/8/2015 **Time Incident:** 08:15 **Facility ID Number:**
County: WILLIAMS **Twp:** 156 **Rng:** 101 **Sec:** 2 **Qtr:**
Location Description:

Submitted By: Julia Traster **Received By:**
Contact Person: Chris Martinez
1801 CALIFORNIA STREET
SUITE 3500
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 1/19/2016 **Clean Up Concluded:** 8/14/2015

Risk Evaluation:

Both personnel on location took precautions to reduce spread of fire and risk to human health.

Areal Extent:

Potential Environmental Impacts:

Condensate impacted soil

Action Taken or Planned:

Location was shut in, fire extinguisher was used and fire department was called to put out fire.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 8/10/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, condensates impacted soils on the well facility after a fire. NDIC retains oversight.